

# STEEL TUBE INSTITUTE

## HSS Design Manual, Volume 3 Connections at HSS Members

### TABLE OF CONTENTS

<b>INTRODUCTION TO DESIGN OF SHEAR AND MOMENT CONNECTIONS FOR HSS</b> .....	1
<b>LIMIT STATES</b> .....	2
Matrix of Limit States for Connections to HSS Columns .....	3
<b>WIDE-FLANGE BEAM SHEAR CONNECTIONS AT HSS COLUMNS</b> .....	4
Single Plate Connections.....	4
Table 3-3.1 Minimum Thickness Table for Punching Shear in Single Plate Connections.....	5
Table 3-3.2 Single Plate Connection Tables.....	6
Single Angle Connections.....	8
Table 3-3.3 Single Angle Connection Tables .....	10
Double Angle Connections.....	12
WT Connections.....	13
Table 3-3.4 WT Connection Tables.....	14
Unstiffened Seat Connections.....	16
Stiffened Seat Connections .....	17
Through-Plate Shear Connections .....	17
High Shear Load Connections .....	18
<b>CONNECTIONS FOR HSS BEAMS</b> .....	19
<b>SHEAR CONNECTION EXAMPLES</b> .....	23
WF Beam to HSS Column Single Plate Connection Example.....	23

WF Beam to HSS Column Single Angle Connection Example.....	26
WF Beam to HSS Column Double Angle Connection Example.....	30
WF Beam to HSS Column WT Connection Example.....	33
WF Beam to HSS Column Unstiffened Seat Connection Example.....	37
WF Beam to HSS Column Stiffened Seat Connection Example .....	41
WF Beam to HSS Column Through-Plate Connection Example.....	47
HSS Beam to HSS Column Double Shear Plate Connection Example.....	51
HSS Beam to HSS Column Seated Connection with Top Angle Example .....	55
HSS Beam to HSS Column End Plate Connection .....	57
Beam to HSS Column High Shear Load Connection Example.....	63
<b>MOMENT CONNECTIONS AT HSS COLUMNS .....</b>	<b>70</b>
Continuous Beam Over HSS Column Connections.....	70
Through-Plate Moment Connections.....	71
Cut-out / Collared Plate Moment Connections.....	71
Welded Tee Flange Moment Connections .....	72
End Plate Moment Connections .....	72
Diaphragm Plate Moment Connections .....	73
Directly Welded Connections.....	73
<b>MOMENT CONNECTION EXAMPLES .....</b>	<b>74</b>
Continuous Beam Over HSS Column Connection Example.....	74
Through-Plate Moment Connection Example.....	84
Cut-Out/Collared Plate Moment Connection Example.....	93
Welded Tee Flange Moment Connection Example .....	102
Directly Welded Moment Connection Example.....	110
Diaphragm Plate Moment Connection Example.....	112